

60 CYCLE SPARK-OVER OF THE NEEDLE-GAP.

POINTS:- X : ONE SIDE GROUNDED.
O : BOTH SIDES INSULATED.

HIGH VOLTAGE
ENGINEERING LABORATORY
PITTSFIELD WORKS
GEN. ELEC. CO.
OCTOBER 8th 1925.